



Inventor: SCHERER ET AL.  
Docket No.: 3616.213US01  
Title: MOLD FOR MAKING A MASONRY BLOCK  
Serial No.: 10/038,639  
Sheet 1 of 12  
REPLACEMENT SHEET

FIG. 2




FIG. 3




FIG. 1






FIG. 3A



BEST AVAILABLE COPY

FIG. 5






FIG. 6




FIG. 7




FIG. 8

FIG. 9





FIG. 4







FIG. 10

FIG. 11






FIG. 12A




FIG. 12B




FIG. 12C

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- BLACK BORDERS**
- IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- FADING TEXT OR DRAWING**
- BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- SKEWED/SLANTED IMAGES**
- COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- GRAY SCALE DOCUMENTS**
- LINES OR MARKS ON ORIGINAL DOCUMENT**
- REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**